










# East 17th Street



## EXPLANATION

-  **MW-9** Groundwater Monitoring Wells Installed by MJA Consulting, Inc.
-  **B-11** Location and Designation of Soil Boring by MJA Consulting, Inc.
-  **VE-10** Location and Designation of Vapor Extraction Wells.
-  **AS-8** Location and Designation of Air Sparging Wells.
-  **D** Location and Designation of Soil Borings by CJA & Associates (1/28/02).

-  **(850)** Benzene Concentration in Groundwater in Micrograms Per Liter ( $\mu\text{g/l}$ ).
-  **100** Contour of Benzene Concentration in Micrograms Per Liter ( $\mu\text{g/l}$ ). Dashed Where Inferred.



Note:  
1. All locations are approximate. Well locations were updated 12/15/03 by survey provided by J.M. Hanks & Associates, dated October 29, 2003.

**CJA** **C. JAMES & ASSOCIATES, INC.**  
Environmental Consultants

Client:  
**BEACON BAY AUTO WASH NO.3**  
**OCHCA Case #90UT99**  
481 East 17th Street, Costa Mesa, California

## SITE PLAN WITH BENZENE CONCENTRATIONS IN GROUNDWATER ON APRIL 27, 2005

Plate 5

Drawn By: H.L. Approved By: H.H. Project Number: 00445 Date: April 2005